

1. Definitely needs a weight limit...
2. The clasps at either end of the chain are too weak. Both were broken within minutes.
3. Tanker punctured the ball in no time, which allowed him to be able to compress the ball enough to tear a good slit in it.
4. After the base was filled with concrete it helped keep the unit from tipping over, but if there were pilot holes on the sides so you could stick (hammer) some steaks in the ground that would help. (Think large tent steaks.)
5. The eyehook that is in the ball still came unscrewed; I believe you mentioned that it was fixed on my model.
6. The center pole visibly bends - may want a thicker pole for heavier breeds.
7. The base portion that is supposed to hold the pole tight never really cinches down. The tightening mechanism should be looked at. I don't think there is enough friction between the plastic and the painted pole for it to hold it in place.
8. The same piece as in #7 is what finally broke and the product became unusable. When the unit was pulled over, the tightening mechanism just snapped in half. No way for it to support the pole any longer.